



U.S. Department of Transportation

National Highway Traffic Safety Administration

# Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

\*\*\* \*\*\* \*\*\*



Case Vehicle (A): 1999 Mercury Type: Villager 4 x 2, 4-door wagon

Driver: 41-year-old male

CDC: 12-FDEW-2, 07-LZEW-2

Veh. (B): 1995 Ford

Type: Mustang GT, 2-door coupe

Driver: 39-year-old female

CDC: 99-0000-0

Veh. (C): Unknown Type: Unknown Driver: Unknown CDC: 99-0000-0

# **SITUATION**

(Slide 1) It was daytime, the sky was clear, and (slide 2) the multi-lane asphalt, limited-access freeway road surface was dry and free of defects. Case vehicle (A) was traveling west at a driver-estimated speed of 89 kph (55 mph) in the center westbound lane. Vehicle (B) was traveling west at an unknown speed in the center westbound lane in front of case vehicle (A). The driver of case vehicle (A) reportedly closed his eyes momentarily, and when he reopened them, the traffic had stopped or slowed rapidly. The driver of case vehicle (A) applied the brakes but was unable to slow down in time, and the front of case vehicle (A) struck the rear of vehicle (B). After the first impact, case vehicle (A) moved toward the south side of the road so as not to block traffic. Unknown vehicle (C) attempted to go around the previous crash by going onto the south shoulder of the road, but struck the left side of case vehicle (A). Ambulance personnel treated the driver of case vehicle (A) at the scene. The driver of vehicle (B) was transported to a local area hospital for minor injuries.

# GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

(Slide 3) Overall damage to case vehicle (A) was moderate. (Slide 4) Direct damage to case vehicle (A) from the first impact extended across the entire frontal plane and overrode the front bumper. (Slide 5) The maximum crush was 32 cm at the left center of the upper radiator support. (Slide 6) Left-side damage to case vehicle (A) from the second impact began 51-cm forward of the left-rear bumper corner and extended 140-cm toward the front. The maximum crush from the second impact was 15 cm, at a point just forward of the left-rear wheel.

Crush profiles were measured for case vehicle (A) (slides 7, 8, 9 and 10) at the level of the bumper and (slides 11, 12, 13 and 14) at the level of the upper radiator support. Using these crush values and the average value at the two levels if the difference was  $\geq$  13 cm, the

WinSMASH accident-reconstruction program was used to determine the impact severity shown below:

		Calculated Velocity Change - kph (mph)				
Vehicle	Variable	Total	Longitudinal	Latitudinal		
Case Vehicle (A)	EBS	28 (18)	-28 (-18)	0 (0)		

Using the WinSMASH accident-reconstruction program, and (slides 15, 16 and 17) a crush profile measured for case vehicle (A), the following impact severity was calculated for the left-side impact:

		Calculated Velocity Change - kph (mph)				
Vehicle	Variable	Total	Longitudinal	Latitudinal		
Case Vehicle (A)	EBS	13 (8)	12 (8)	5 (3)		

# DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)

# **Exterior**

(Slide 18) In the front, the bumper cover was torn off, (slide 19) and the bumper, the grille, the fascia, both headlight assemblies, the upper radiator support, the radiator, the hood, both hood hinges and the hood latch were damaged. The hood latch was jammed closed. (Slide 20) The rear edge of the hood was elevated, but it did not contact the windshield, (slide 21) which was spiderwebbed from occupant contact.

On the left side, (slide 22) the quarter panel, the lower C-pillar, and the left-rear door were crushed inward. The left-rear door was jammed closed. The left-rear wheel/tire was damaged (the rear wheel had been changed to a space-saver spare), the lower D-pillar was deformed, and (slide 23) the fender was crushed rearward. There was no significant change in the left wheelbase.

On the right side, (slide 24) the fender was crushed rearward. (Slide 25) There was no other right-side damage and (slide 26) no significant change in the right wheelbase.

(Slide 27) The rear bumper cover was torn off (probably when the vehicle was towed from the accident scene or to the salvage yard), but there was no other damage to the rear of the vehicle.

# **Interior**

This vehicle was equipped with steering-wheel and passenger frontal-impact airbags, and (slides 28, 29 and 30) both deployed in the frontal impact. (Slide 31) There was no damage to the steering-wheel or (slides 32 and 33) passenger airbag module covers. (Slide 34) There was no damage to the steering-wheel rim or spokes, and (slide 35) there was no apparent horizontal or vertical displacement of the steering column. (Slide 36) The forward portion of the plastic panel on the left-front door was cracked. (Slide 37) The left-rear door panel and C-pillar were deformed by the second impact. (Slide 38) The windshield was cracked by driver hand contact. (Slides 39, 40 and 41) Except for scuff marks on the knee bolster, there was no other damage to the driver area. There was no damage to the (slides 42 and 43) center-front, (slide 44) right-front, (slide 45) second-seat, or (slide 46) third-seat areas.

# OCCUPANT KINEMATICS AND INJURIES

(Slide 47) The 5-ft, 8-in, 190-lb, 41-year-old male driver was <u>not</u> wearing the three-point belt, but the frontal-impact airbag deployed. (Slide 48) There were no witness marks on the plastic Dring.

On impact, the driver moved forward and upward relative to the vehicle interior. He sustained abrasions to the center of his forehead and to his nose, (slide 49) probably due to direct contact with the left sunvisor, (slides 50 and 51) as evidenced by skin transfers on the visor fabric, but possibly due to contact with the upper A-pillar, (slide 52) as evidenced by a few short hairs embedded in the fabric. He sustained abrasions to the left and right knees due to direct contact with the knee bolster, (slide 53) as evidenced by scuff marks on the plastic knee bolster cover.

The driver's hands reportedly came off of the steering wheel at the time of the crash, probably due to airbag fling. The left hand probably contacted the windshield, (slide 54) as evidenced by the spiderweb crack in the windshield, but no injury was reported to his left hand. His right hand probably contacted the rear-view mirror, (slide 55) as evidenced by the short hairs and oil on the mirror, but no injury was reported to the right hand. His left hip may have contacted the left-front door armrest, (slide 56) as evidenced by a scuff mark, but no injuries were reported from this contact.

The following table and attached drawing (slide 57) summarize the injuries for the driver of case vehicle (A).

Occupant: Driver Restraints: 3-point belt <u>not</u> worn; airbag deployed

Age: 41 years Stature: 173 cm (5 ft, 8 in)

Gender: Male

Mass: 86 kg (190 lb)

			Injury Source	
Injury Description	A.I.S.	Definite	Probable	Possible
Abrasion, center of forehead	1		Sunvisor	A-pillar
Abrasion, nose	1		Sunvisor	A-pillar
Abrasion, right knee	1	Knee bolster		
Abrasion, left knee	1	Knee bolster		
•				
Maximum A.I.S. Level	1			
njury Severity Score	1			

Duplicate columns 1-8 Module G I Format from the previous card. 9 10	0 2	GENERAL INFORMATION	GI-1
Тіме		ENVIRONMENTAL CONDITIONS	
DATE OF COLLISION		CONSTRUCTION ZONE	
	у у	(0) NO (1) YES (9) UNKNOWN	<u>O</u> 33
HOUR OF COLLISION	4	ROAD ALIGNMENT VERTICAL PLANE	
LOCATION		(1) LEVEL (2) CREST OF HILL	]
STATE:		(3) SLOPE (2%) (4) BOTTOM OF HILL (9) UNKNOWN	34
STATE FIPS CODE	25 26	ROAD ALIGNMENT HORIZONTAL PLANE	
AREA		(1) STRAIGHT	1
(1) URBAN (2) RURAL (9) UNKNOWN	1/27	(2) CURVE (3) T - SHAPED (4) Y - SHAPED (7) OTHER:	35
ENVIRONMENTAL CONDITIONS		(9) UNKNOWN SURFACE COVERING	
LIMITED-ACCESS HIGHWAY		(10) DRY	10
(0) NO (1) YES (9) UNKNOWN	28	(21) WATER - DAMP (22) WATER - WET	36 37
ROAD, TOTAL TRAFFIC LANES		(23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN	
(FOR CASE VEHICLE)  (1) 1-LANE		(31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN	
(2) 2-LANES (3) 3-LANES	5	(41) ICE	
(4) 4 OR MORE LANES (5) DIVIDED, 4 OR MORE LANES	29	(51) SLUSH (61) SPILLED GRAVEL	
(6) PARKING LOT/DRIVEWAY (7) OTHER:		(71) OTHER: (99) UNKNOWN	
(9) UNKNOWN INTERSECTING RD, TOTAL LANES		VISIBILITY LIMITATION (FOR CASE VEHICLE)	
CHOOSE FROM ABOVE LIST, OR	8	(0) NONE (1) CLOUDY/DARK	0
(8) NOT APPLICABLE	<u>0</u>	(2) FOG (3) SMOKE	38
TYPE OF BOAD SUPEASE		(4) WINDSHIELD CONDITION (5) GLARE	
TYPE OF ROAD SURFACE  (1) ASPHALT		(6) RAIN (7) OTHER:	
(2) CONCRETE (3) GRAVEL		(8) ICE/SNOW (9) UNKNOWN	
(4) MORE THAN ONE (CIRCLE EACH) (7) OTHER:		VISIBILITY OBSTRUCTION (FOR CASE VEHICLE)	
(9) UNKNOWN		(0) NONE	
ROAD DEFECTS		(1) BUILDING (2) SIGN	$\left  \begin{array}{c} O \\ \hline O \end{array} \right $
(0) NO (1) YES	0	(3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE	
(9) UNKNOWN	32	(5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER:	
		(8) PARKED VEHICLE (9) UNKNOWN	

		GENERAL INFORMATION GI-2
ENVIRONMENTAL CONDITIONS  SPEED LIMIT  (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-60 35 (3) 61-70 40 (4) 71-79 45 (5) 80-85 50 (6) 86-90 55 (7) 91-105 60 (8) OVER 105 65 (9) UNKNOWN	8 40	MECHANICAL MALFUNCTION  WAS THERE MENTION OF A MECHANICAL MALFUNCTION IN CASE VEHICLE  (0) NO (1) YES (2) YES, DID NOT CONTRIBUTE TO ACCIDENT (9) UNKNOWN
(0) NONE (1) RAIN (2) SNOW (3) HAIL (4) FREEZING RAIN/SLEET (7) OTHER: (9) UNKNOWN  RATE OF PRECIPITATION  (1) LIGHT/MIST (2) MODERATE (3) HEAVY (8) NOT APPLICABLE (9) UNKNOWN  TEMPERATURE  (0) BELOW -15° C BELOW 5° F (1) -15 TO -6 5 TO 22 (2) -5 TO -1 23 TO 31 (3) 0 TO 2 32 TO 36 (4) 3 TO 5 37 TO 41 (5) 6 TO 15 42 TO 59 (6) 16 TO 25 60 TO 77 (7) 26 TO 35 78 TO 95 (8) OVER 35 OVER 96 (9) UNKNOWN	<u>8</u> 42 <u>5</u> 43	THE FOLLOWING SECTION SHOULD BE FILLED OUT IF A MECHANICAL MALFUNCTION IS RECOGNIZED OR SUSPECTED.  CIRCLE ITEMS INVOLVED. SUPPORT ANY ITEMS CIRCLED WITH COMMENTS.  BRAKE SYSTEM DRIVER CONTROLS EXHAUST SYSTEM POWER TRAIN STEERING SYSTEM FUEL SYSTEM SUSPENSION SYSTEM VISIBILITY ITEMS ELECTRICAL SYSTEM TIRES  THROTTLE CONTROLS UNKNOWN OTHER:
CROSSWIND  (0) NONE (1) LIGHT (2) STRONG (3) GUSTY & STRONG (9) UNKNOWN  LIGHT CONDITIONS  (1) DAYLIGHT (2) DAWN (3) DUSK (4) DARK, LIGHTED (5) DARK, UNLIGHTED (6) DARK, UNKNOWN IF LIGHTED (9) UNKNOWN	<u>0</u> <u>45</u>	
		-

			GENERAL INFORMATION	GI-3
(	CASE VEHICLE AND OBJECT  (0) NO (1) YES (9) UNKNOWN  CASE VEHICLE ROLLOVER  (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT	<b>Q</b> 47	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE)  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	<b>2</b> 55
	(3) YES, SEQUENCE UNKNOWN (9) UNKNOWN  CASE VEHICLE RAN OFF ROADWAY  BEFORE FIRST IMPACT)  (0) NO (1) YES (9) UNKNOWN	<b>2</b>	DRIVER IMPAIRMENT  DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE)  (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER	<u>O</u> 56
N C	MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE (0) NO (1) YES (9) UNKNOWN		DRIVER ALCOHOL BAC (CASE VEHICLE)  (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	<b>8</b> 0 58
C	CASE VEHICLE AND CONTACTED STOPPED VEHICLE  (0) NO (1) YES (9) UNKNOWN	51	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	<u>O</u> 59
S C	TOPPED CASE VEHICLE AND ONTACTED VEHICLE  (0) NO (1) YES (9) UNKNOWN	52	LIST IMPAIRMENTS MENTION	ED:
0	OTAL NUMBER F VEHICLES CONTACTED Y CASE VEHICLE IN CRASH  (8) 8 OR MORE (9) UNKNOWN	<u>Z</u>	Post - Crash Detail  MANNER CASE VEHICLE LEFT SCENE	
	NY FIRE IN THIS CRASH FOT JUST CASE VEHICLE)  (0) NO (1) YES (9) UNKNOWN	54	(1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE* (4) TOWED, REASON UNKNOWN (9) UNKNOWN	2 60

į	(c) hit the	lett-Side	of CM.	of vehicle  vehicle (A).	OTHER VEHICLE	E (B): <u>1995 For</u>	ed Mustan
					I HIND VEHICLE	(C):	
				· .			NC
			· Sno	ed the tree			
			Spe	ed limit 70 mph			
		·					
			• B2 ← •	B1			
<b>1</b> .					✓ A1	[]	
ři.			. A3		<b>√</b> C1		
ı			1 0	2			
	h ind second are real are		INTERCEP. NEWS.		Company of the state of the sta		
					Cor	ncrete median barrier	,
						· <b></b>	

Duplicate columns 1-8 Module O V Format C from the previous card. 9 10 1	1 12	OTHER VEHICLE C	DV-1
MAKE: FORD  MODEL: Mustawg GT, 2-door	и СО	CARGO:	
VIN <u>1 FALP42</u>	T8	S F 00000	
MANUFAC/BODY CODE $\frac{1}{30}$ $\frac{2}{2}$ $\frac{1}{2}$ MAKE/MODEL CODE $\frac{0}{2}$ $\frac{3}{2}$ MODEL YEAR $\frac{1}{39}$ $\frac{9}{9}$ VEHICLE MASS (kg) $\frac{0}{43}$ $\frac{0}{2}$ $\frac{1}{2}$ $\frac{5}{2}$ $\frac{1}{2}$	34 4 4 38 5	VEHICLE TYPE  PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (17) PICKUP CAR (20) UNKNOWN PASSENGER VEHICLE BODY (24) SUB-MINI (25) MINI (26) SUB-COMPACT (27) COMPACT (28) INTERMEDIATE (29) FULL	<b>2</b> 7/56 57
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER	48 <u>O</u> 	MULTIPURPOSE PASSENGER VEHICLE  (14) SMALL UTILITY (WHEELBASE LESS THAN 107", E.G. JEEP, BRONCO)  (15) LARGE UTILITY (WHEELBASE MORE THAN 107", E.G. PANEL TRUCK, SUBURBAN)  (16) PICKUP TRUCK WITH CANOPY/SHELL COVER  (17) PICKUP CAR WITH CANOPY/SHELL COVER  (21) MOTOR HOME  (22) PICKUP TRUCK WITH SLIDE-IN CAMPER  (23) PICKUP CAR WITH SLIDE-IN CAMPER  (31) CHASSIS-MOUNTED CAMPER	
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	54	TRUCK (11) VAN (12) PICKUP TRUCK (13) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (30) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN)	
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	55	(34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S)  BUS (40) UNKNOWN BUS TYPE (41) SCHOOL BUS (42) INTERCITY BUS (BETWEEN CITIES) (43) TRANSIT BUS (INTRACITY) (44) STREETCAR (ON TRACKS) (68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER)	T T
₹. ,		(99) UNKNOWN  WHEELBASE (cm) (999) UNKNOWN	2 5 7 58 59 60

**Duplicate columns 1-8** from the previous card. Module 0 V Format 0 2 11 12

OTHER VEHICLE

OV-2

# **ORIGINAL SPECIFICATIONS**

257 cm Wheelbase

Front Overhang

 $\frac{1}{22} \frac{0}{24} \text{ cm}$ 

**Curb Weight** 

Rear Overhang

 $\frac{1}{25}$  0  $\frac{2}{27}$  cm

Average Track Width 13 5 1 cm

Undeformed End Width (UEW) 1/28 4 5 cm

Overall Length

$$\frac{4}{16}$$
  $\frac{6}{18}$  cm

**Engine Displacement** 

 $\frac{5}{31} \cdot \frac{0}{32}$ 

Overall Width (OAW) 1 8 2 cm


Engine: # of Cylinders

08

# **VEHICLE DAMAGE**

MEASUREMENTS IN CENTIMETERS

# This vehicle was not inspected



# FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

9999cm

Front-End Overlap (Percent) = DDL

9 9%

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)

99%

Duplicate columns 1-8 Module O V Format 0 4 from the previous card.	OTHER VEHICLE OV-1
MAKE: UNKNOWN MODEL: UNKNOWN	CARGO:
VIN 999999999	9900000
MANUFAC/BODY CODE	VEHICLE TYPE  PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (17) PICKUP CAR (20) UNKNOWN PASSENGER VEHICLE BODY (24) SUB-MINI (25) MINI (26) SUB-COMPACT (27) COMPACT (28) INTERMEDIATE (29) FULL  MULTIPURPOSE PASSENGER VEHICLE (14) SMALL UTILITY (WHEELBASE LESS THAN 107*, E.G. JEEP, BRONCO) (15) LARGE UTILITY (WHEELBASE MORE THAN 107*, E.G. PANEL TRUCK SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (21) MOTOR HOME (22) PICKUP CAR WITH SLIDE-IN CAMPER (23) PICKUP CAR WITH SLIDE-IN CAMPER (31) CHASSIS-MOUNTED CAMPER  TRUCK (11) VAN (12) PICKUP TRUCK (13) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK SUBURBAN) (16) PICKUP TRUCK WITH SLIDE-IN CAMPER (22) PICKUP TRUCK WITH CANOPY/SHELL COVER (23) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (22) PICKUP TRUCK WITH CANOPY/SHELL COVER (23) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN)
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	(34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S)  BUS (40) UNKNOWN BUS TYPE (41) SCHOOL BUS (42) INTERCITY BUS (BETWEEN CITIES) (43) TRANSIT BUS (INTRACTY) (44) STREETCAR (ON TRACKS)  (68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER)  (99) UNKNOWN  WHEELBASE (CM) (999) UNKNOWN

Duplicate columns 1-8 from the previous card.	Module O V	Format <u>0</u> <u>2</u>	OTHER	R VEHICLE	OV-2
		ORIGINAL SE	PECIFICATIONS		
Wheelbase	9999	cm	Front Overhang	999	em .
Curb Weight	999	kg	Rear Overhang	6 9 9	:m
Average Track Width	999	cm	Undeformed End Width (UEW)	6 6 6	m
Overall Length	<u>9</u> <u>9</u> <u>9</u> <sub>18</sub>	cm	Engine Displacement	$\frac{9}{31} \cdot \frac{9}{32}$	L
Overall Width (OAW)	9 9 9	cm	Engine: # of Cylinders	<b>7 9</b> 33	

# **VEHICLE DAMAGE**

Unknown vehicle

# FRONTAL CRASH OVERLAP Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Front-End Overlap (Percent) = $\frac{DDL}{UEW}$ Vehicle Overlap (Percent) = $\frac{DDL + 1/2 (OAW - UEW)}{OAW}$ $\frac{9}{35}$ $\frac{9}{37}$ cm $\frac{9}{35}$ $\frac{9}{37}$ $\frac{9}{37}$ $\frac{9}{37}$ $\frac{9}{37}$ $\frac{9}{37}$ $\frac{9}{37}$ $\frac{9}{37}$ $\frac{9}{37}$ $\frac{9}{37}$ $\frac{9}{37}$


Duplicate columns 1-8 Module V D Format 0 4 from the previous card.	VEHICLE DESCRIPTION	VD-1
MAKE: Meriury  MODEL: Villager, 4-door nini-	CARGO:	
VIN 4 M 2 X V 1 1	T 6 X D 0 0 0	<b>O</b> <u>O</u> 29
MANUFAC/BODY CODE	STOLEN VEHICLE	
MAKE/MODEL CODE $0962$	(0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	<u>8</u>
MODEL YEAR	. (6) 6.11.11.6.11.	
VEHICLE MASS (kg) 0 0 1 8 1 3	BODY STRUCTURE	7
ODOMETER (km) (ENTER 9'S IF UNKNOWN) (ENTER 8'S IF ELECTRONIC)  49  54	(1) BODY & FRAME (2) UNITIZED (3) INTEGRAL-STUB FRAME (4) BODY & PLATFORM FRAME (E.G. VW BUG)	63
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)  55 mph  56	(5) PARTIALLY UNITIZED (7) OTHER: (9) UNKNOWN	
TRAVELING SPEED (km/h)  O  8  9  59		
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	TRANSMISSION  (0) NONE (1) AUTOMATIC (2) MANUAL (9) UNKNOWN	<u></u>
VEHICLE TYPE	LOCATION OF TRANSMISSION	
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE  60 61	SELECTOR LEVEN	3
(ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP	(1) FLOOR (2) CONSOLE (3) COLUMN	65
(14) 4-DOOR SEDAN (15) STATION WAGON (16) CONVERTIBLE (18) OTHER PASS. VEH.: (19) PASSENGER VEHICLE, TYPE UNKNOWN	(7) OTHER: (9) UNKNOWN	
MULTIPURPOSE PASSENGER VEHICLE (21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO)	STEERING	,
(22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME	(1) POWER (2) MANUAL (9) UNKNOWN	66
TRUCK (31) PICKUP TRUCK, UNKNOWN (32) PICKUP TRUCK, SMALL (DOWNSIZED) - (33) PICKUP TRUCK, LARGE	BRAKES - (1) POWER (2) MANUAL	1
(99) UNKNOWN	(9) UNKNOWN	67

* <b>-</b>		VEHICLE DESCRIPTION \	/D-2
TYPE OF BRAKES  (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	<u>2</u>	WHEELBASE <i>(cm)</i> (999) Unknown	Z & 5 76 77 78
BRAKE ANTI-LOCK DEVICE  (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN  AIR CONDITIONING IN VEHICLE	<u>Z</u>	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED  (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER	<b>O</b> 79
(0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	8 70	(9) UNKNOWN	
TYPE OF DRIVE  (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN	<u>2</u>	FIELD INVESTIGATOR INSTRUCTIONS:  1. INDICATE CRUSHED AREAS BY <u>OUT-LINING NEW PERIMETER</u> OF VEHICLE AND <u>SHADING THE DAMAGED AREAS</u> ON THE LARGE SKETCH ON PAGE VD-3.	
DUAL REAR WHEELS  (0) NO (1) YES (9) UNKNOWN	72	USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE.  2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE	-
ORIGINAL TYPE OF RESTRAINT SYSTEM  (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	<u>3</u>	EXAMPLES BELOW AS A GUIDE.  3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR.  4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE.  EXAMPLES:	
EQUIPPED WITH ROLL BAR  (0) NO (1) YES (9) UNKNOWN	<u>0</u>	FRONT OR REAR	
TYPE OF ROOF  (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	<u>J</u> 75	ROOF (REFERENCE TO TOP OF DOOR SILL)	

VEHICLE DESCRIPTION Module V D Format 0 2 11 12 Duplicate columns 1-8 VD-3 from the previous card. **ORIGINAL SPECIFICATIONS** 285  $\frac{1}{22}$   $\mathcal{O}$   $\frac{1}{24}$  cm Wheelbase Front Overhang  $\frac{1}{25} \quad \frac{1}{6} \quad \frac{0}{27} \text{ cm}$   $\frac{1}{28} \quad \frac{6}{30} \quad \frac{0}{30} \text{ cm}$ 18/3 kg **Curb Weight** Rear Overhang Undeformed End Width (UEW) 4 9 5 cm  $\frac{3}{31} \cdot \frac{3}{32}$ Overall Length **Engine Displacement** Overall Width (OAW) 10 9 0 cm Engine: # of Cylinders

# **VEHICLE DAMAGE**

# MEASUREMENTS IN CENTIMETERS



# FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

 $\frac{1}{35} \frac{6}{6} \frac{0}{37} \text{ cm}$ 

Front-End Overlap (Percent) = DDL UEW

**9 8** %

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)
OAW

9 8 %

Duplicate columns 1-8 Module D // from the previous card.	A Format 0 2 11 12	DAMAGE DA-1
- Primary	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	1/22	Jeh(B)
IMPACT SPEED (km/h)	<u>q q q</u>	9 9 9 35 36 37
ESTIMATED BY		<u> </u>
CRUSH (cm)	$\frac{0}{18} \frac{3}{19} \frac{2}{20}$	9 9 9 39 40 41
CDC #1	12. FPEW. 2	99.0000.0
CDC #2	98.0000.0	99.0000.0
Duplicate columns 1-8 Module D A from the previous card.	Format <u>0</u> <u>3</u>	
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	<b>Z</b>	veh (c)
IMPACT SPEED (km/h)	$\frac{9}{9} \stackrel{13}{\stackrel{9}{{_{16}}}} q$	9 9 9 35 36 37
ESTIMATED BY	1	
CRUSH (cm)	$O_{18} = \frac{17}{19} = \frac{5}{20}$	$\frac{9}{9} \frac{9}{40} \frac{9}{41}$
CDC #1	07 LZEW.Z	99.0000.0
CDC #2	98.0000.0	99.0000. <u>0</u>
Codes		
EVENT NUMBER	IMPACT SPEED ESTIMATOR	CRUSH
(8) NOT APPLICABLE (9) UNKNOWN	(1) INVESTIGATOR (2) DRIVER	(998) NOT APPLICABLE (NO VEHICLE/DAMAGE)
IMPACT SPEED	(3) POLICE (4) "CRASH" PROGRAM (5) OTHER COMPLITED PROGRAM	(999) UNKNOWN
(998) NOT APPLICABL (999) UNKNOWN	(5) OTHER COMPUTER PBOGRAM  E SPECIFY:  (7) OTHER:  (8) NOT APPLICABLE  (NO VEHICLE/NO IMPACT)	CDC (9800000) NOT APPLICABLE (9900000) UNKNOWN

DAMAGE Duplicate columns 1-8 Module D A Format 0 1 DA-2 from the previous card. 10 MAXIMUM SHEET METAL CRUSH (cm) (999) UNKNOWN 0 3 2 000 FRONT RIGHT SIDE 0 0 0 1 5 REAR LEFT SIDE  $\frac{\mathcal{O}}{25}$   $\frac{\mathcal{O}}{27}$ O 0 0 ROOF **OTHER** CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER? NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL. (0) NO (1) YES **EVENT NUMBER** IMPACT CONFIGURATION IMPACT LOCATION **OBJECT/VEHICLE** CONTACTED (1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE FOR CODES, SEE TABLE FOR CODES, SEE TABLE (3) ON ROADSIDE ON PAGE DA-3. ON PAGE DA-4. (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN #1 #2 #3 42 #4 #5 56 #6 59 #7 -

## DAMAGE DA-3

# CODES FOR IMPACT CONFIGURATION

# **FRONT OF CASE VEHICLE**

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

# LEFT SIDE OF CASE VEHICLE

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T) (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

# **REAR OF CASE VEHICLE**

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

# RIGHT SIDE OF CASE VEHICLE

- (41) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (42) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
  (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

# OTHER -

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

# **ROLLOVER**

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

# UNKNOWN

(99) IMPACT TYPE <u>UNKNOWN</u>

# DAMAGE DA-4

# CODES FOR VEHICLE/OBJECT CONTACTED

### VEHICLE/OBJECT GROUPS RUS NO OBJECT (00) (40) UNKNOWN BUS TYPE (01) - (39) PASSENGER VEHICLE & TRUCK (41) SCHOOL BUS (40) - (69) OTHER VEHICLE (42) INTERCITY BUS (BETWEEN CITIES) (70) - (76) PEDESTRIAN & ON-ROADWAY OBJECT (43) TRANSIT BUS (INTRACITY) (77) - (97) OFF-ROADWAY OBJECT (44) STREETCAR (ON TRACKS) OTHER (DESCRIBE) UNKNOWN (99) MOTORCYCLE (50) UNKNOWN MOTORCYCLE TYPE PASSENGER VEHICLE (51) 1 - 75 cc (52) 76 - 125 cc (53) 126 - 250 cc (02) LARGE (03) LIMOUSINE (17) PICKUP (54) 251 - 500 cc (20) UNKNOWN PASSENGER VEHICLE BODY (55) 501 - 750 cc (24) SUB-MINI (56) 751 cc + (25) MINI (57) 3-WHEELS (OR WITH SIDECAR) (26) SUB-COMPACT (27) COMPACT SPECIAL PURPOSE VEHICLE (28) INTERMEDIATE (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE) (29) FULL (61) SNOWMOBILE (62) ATV (ALL TERRAIN VEHICLE) (63) AMPHIBIOUS VEHICLE SIZE **WHEELBASE** (64) FARM VEHICLE (65) CONSTRUCTION VEHICLE < 2286 mm ( < 90") (66) TRAILER, PRIVATE (CAMPER) SUB-MINI MINI 2286 - 2412 mm (90" - 94.9") (67) TRAILER, COMMERCIAL (CARGO) SUB-COMPACT 2413 - 2539 mm (95" - 99.9") (68) TRAIN (CARS) COMPACT 2540 - 2666 mm (100" - 104.9") (69) LOCOMOTIVE (ENGINE, SWITCHER) INTERMEDIATE 2667 - 2793 mm (105" - 109.9") FULL 2794 - 2920 mm (110" - 114.9") LARGE 2921 - 3174 mm (115" - 124.9") **OBJECT** (70) PEDESTRIAN LIMOUSINE > 3175 mm (> 125°) (71) BICYCLIST, OTHER PEDALCYCLIST (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING **MULTIPURPOSE PASSENGER VEHICLE** ANIMAL, CART) (11) SMALL VAN (MINI) (73) LARGE ANIMAL (12) PICKUP (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM (14) SMALL UTILITY (WHEELBASE LESS THAN 107", OTHER VEHICLE, FALLEN TREE, ROCKS) E.G. JEEP, BRONCO) (75) ROCKS (15) LARGE UTILITY (WHEELBASE MORE THAN 107", (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65)) E.G. PANEL TRUCK, SUBURBAN) (77) SIGN POST, UTILITY POLE, TREE (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (78) DITCH (17) PICKUP CAR WITH CANOPY/SHELL COVER (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X (21) MOTOR HOME (80) GROUND (ROLLOVER ONLY) (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (81) CURB (DAMAGE PRODUCING IMPACTS ONLY) (23) PICKUP CAR WITH SLIDE-IN CAMPER (82) CULVERT (31) CHASSIS-MOUNTED CAMPER (83) FENCE (84) HYDRANT, SHORT POST, STUMP (85) SMALL POST/TREE, RURAL MAIL BOX, MILE TRUCK MARKER, DELINEATOR (11) SMALL VAN (E.G. ECONOLINE) (86) BUILDING (12) PICKUP TRUCK (87) PIER, PILLAR, BRIDGE SUPPORT (13) UNKNOWN LIGHT TRUCK (88) ABUTMENT, RETAINING WALL (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (89) BRIDGE RAIL (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (90) GUARD RAIL, LEADING SECTION (91) GUARD RAIL, MIDDLE OR UNKNOWN (92) GUARD RAIL, TRAILING SECTION (93) GUARD POST (TIMBER, METAL, CONCRETE) (30) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK (94) CABLE, FENCE BARRIER (95) CONCRETE BARRIER (MEDIAN) (35) TRUCK-TRACTOR (BOBTAIL) (96) IMPACT ATTENUATOR

(97) BREAKAWAY FEATURES

(36) CHASSIS-CAB

<del>\*</del> .

(37) UNKNOWN HEAVY TRUCK

(38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S)

	R Format 0 1 10 11 12		SH RECONSTRUC or AV	CTION CR-1
	CASE VEHICLE	PRIMARY IMPACT	CASE VEHICLE S	ECONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13		2 47	
ΔV (km/h) TOTAL	14 15 16	$\frac{9}{32} \frac{}{33} \frac{}{34}$	<del>9</del> <del>-</del> 48 <del>49</del> 50	<del>9</del> <del></del>
LONGITUDINAL*	9	<del>9</del> ————————————————————————————————————	9	9
LATERAL*	9	9	9	9
NOTE: THESE $\Delta V$ COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76
EXAMPLES: $10 \text{ km/h} = \pm Q \underline{1} Q$ -7 km/h = $\pm Q \underline{Q} \underline{Z}$				
ENERGY DISSIPATED BY CRUSH (kj)	<u>9</u>	$\frac{9}{43} = {}$	9	9
RECONSTRUCTION				
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	12		<u>O</u> <u>&amp;</u>	
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT				
INSPECTED MODE				
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	5 31	. <b>ع</b> د	<u>5</u> 65	
COMPUTER PROGRAM SPECIFY:				

	R Format 0 2		SH RECONSTRUC OF EBS	TION CR-2		
		PRIMARY IMPACT	CASE VEHICLE SE	ECONDARY IMPACT		
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE		
EVENT NUMBER	13		<del>2</del> 47			
EBS (km/h) TOTAL	0 2 8	9 — 32 33 34	9	9		
LONGITUDINAL*	$\frac{-028}{17}$	9	9	$\frac{9}{69} = {72}$		
LATERAL*	+000	9 —	9-	9-		
NOTE: THESE EBS COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76		
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = <u>:</u> <u>0</u> <u>0</u> Z						
ENERGY DISSIPATED BY CRUSH (kg)	0 0 5 6	9	9	$\frac{q}{77}$ ${80}$		
RECONSTRUCTION						
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	2 2 29 30		08			
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64			
NOT RECONSTRUCTED BECAUSE						
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE	-	·				
BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED			-	·		
MODE						
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	<del>2</del> 31	ـ عد	5 65	-		
COMPUTER PROGRAM SPECIFY: NIMSMAS h		-				

Duplicate columns 1-8 from the previous card.

Module <u>C</u> <u>R</u> Format <u>0</u> <u>3</u> 10 11 12

CRASH RECONSTRUCTION

CR-3

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C  $_{\rm 1}$  TO C  $_{\rm 6}$  FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.


CASE VEHICLE

**LOCATOR** 

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L
1	Frontal Plane	Front bumpen BC to BC
2	Slem forward of Lt. Rear BC	Begin same



DL <u>/60</u>

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other <u>Average</u>d 162
- (9) Unknown

**CRUSH PROFILE IN CENTIMETERS** 

			ole below is a s	separate rec	ord (card).	Du	plicate col	umns 1 - 1	2 for each	n complete	d line.
Specific Impact Number	Plane of Impact C-Measur.	Direct Length (DDL)	Damage Max Crush	Field L	C <sub>1</sub>	C <sub>2</sub>	C <sub>3</sub>	C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	±D
1	1	160		135	23	21	20	19	21	25	0
	FREESPACE				-12	- 4	-2	-2	-6	-12	
1	2		57	140	52	57	51	50	42	45	0
	FREE SPACE		-25	-	-25	-25	-25	-25	-z5	-25	
	Results				1/27	15/	18/26	17/25	15/1	13/20	
1	5	160	032	140	019	024	018	017	015		+000
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
2	4	140	15	164	0	11	15	11	5	0	+102
									-		
÷ ,						-					
2	4	140	015	164	000	011	015	011	005	000	+102

Duplicate columns 1-8 from the previous card.	Module C R Forma	at <u>0 4</u>		Crash F	RECONS	STRUCT	ION	CR-4
2. MEASU IMPACT 3. D IS PO 4. USE TH	CRASH RECONSTRUCTION  THE C <sub>1</sub> TO C <sub>6</sub> FROM DRIVER S, REAR TO FRONT IN SIDE  DISTIVE IF MEASURED TO A R  THE CENTER OF THE WHEELB  THE WHEELB	TO PASSENGER IMPACTS. POINT FORWARD ASE AS THE CG.	SIDE IN FRONT	OR REAR RIGHT OF THI		LO	ER VEH	
Specific Impact No.	Location of	Direct Dama	ıge		Locat	ion of Fi	eld L	
- ·								
PLANE: (1) Bumper (2) Above Bump (3) Sill (4) Above Sill (5) Other (9) Unknown	_ /_	C6 C5 C4 C3 C2 C1		TERS Duplicate col	DL UDL	2 for each		d line
Specific Plane Impact of Impact Number C-Measur.	Direct Damage Length Max (DDL) Crush	Field L	C <sub>1</sub> C <sub>2</sub>	C <sub>3</sub>	C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	±D
			-					
1 <b>9</b>	999 999	21 22 23 2	19 99 4 4 25 26 27 28 2	9 9 9 9 30 31 32	999 33 34 35	999 36 37 38	999 39 40 41	+ 999 42 43 44 45
					-		•	

999 999 999 999 999 999 999 999 +999

Duplicate columns 1-8 Module W T Format from the previous card. 9 10	0 1	WHEELS AND TIRES WT-1
WHEELSDAMAGED  (0) NO (1) YES (9) UNKNOWN  RI  CHANGE OF TOWNSON	F <u>O</u>	SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S)  LF
TIRE TREAD TYPE  (1) REGULAR  (2) SNOW  (3) SLICKS  (4) ALL WEATHER (MS)  (7) OTHER:  (9) UNKNOWN  LP	4 4	55 55
CARCASS CONSTRUCTION  (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN  LR	3 3 3	-
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS. NOTES:		

			BEST AVAILA					
Duplicate columns 1-8 Module F T Format from the previous card.	0 1	FUEL AND FUEL TANKS	FT-1					
- TYPE OF PROPULSIVE FUEL  (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE  (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	21					
- MAIN TANK LOCATION	<u>322</u>	AUXILIARY TANK LOCATION	888					
MAIN FILLER CAP LOCATION	<u>Z 13</u>	AUXILIARY FILLER CAP LOCATION	8 8 8 8 E 27					
MAIN TANK MATERIAL	20	AUXILIARY TANK MATERIAL	<b>8</b> 28					
TANK AND	TANK AND FILLER CAP LOCATION CODES							
	GIT (LONGITE							

- (1) BEHIND KICK-UP
- (2) IN KICK-UP
- (3) BETWEEN KICK-UP & COWL
- (4) FORWARD OF COWL
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

# SECOND DIGIT (LATERAL)

- (1) LEFT OF FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) RIGHT OF FRAME
- (4) DUAL, RIGHT & LEFT TANKS
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

# THIRD DIGIT (VERTICAL)

- (1) BELOW FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) ABOVE FRAME
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

# **TANK MATERIAL CODES**

- (1) STEEL
- (2) ALUMINUM
- (3) PLASTIC
- (7) OTHER

=

- (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN

Module F L Format 0 1 Duplicate columns 1-8 FUEL LEAKAGE FL-1 from the previous card. 9 10 DID FUEL LEAKAGE RESULT FROM A CRASH EVENT (0) NO KNOWN LEAKAGE SKIP PAGE. (1) YES COMPLETE PAGE. 1 11 111 IV **LEAK LEAKING** COMPONENT TYPE OF SEVERITY LOCATION **EVENT** NUMBER COMPONENT SOURCE DAMAGE OF DAMAGE OF LEAK NUMBER #1 14 15 21 #2 23 29 #3 30 31 37 #4 39 #5 53 LEAKING COMPONENT IV SEVERITY OF DAMAGE TANK AREA EEC SYSTEM (CONTINUED) (1) MINOR (2) MODERATE (11) MAIN FUEL TANK (INCLUDING (33) VAPOR RECOVERY HOSES (3) SEVERE VAPOR RECOVERY DOME) (CANISTER TO CARBURETOR) (4) DISCONNECTED/DEFEATED (12) AUXILIARY FUEL TANK (34) LIQUID-VAPOR SEPARATOR (9) UNKNOWN (13) MAIN TANK FILLER TUBE (UNLESS PART OF TANK) (14) MAIN TANK CAP (GAS CAP) (35) CANISTER (15) AUXILIARY TANK FILLER TUBE (39) EEC SYSTEM, DETAILS LOCATION OF LEAK (16) AUXILIARY TANK CAP (GAS CAP) UNKNOWN (19) TANK AREA, DETAILS UNKNOWN FIRST DIGIT (LONGITUDINAL LOCATION) (49) ENGINE COMPARTMENT. **DELIVERY SYSTEM** COMPONENT UNKNOWN (1) F. FORWARD OF COWL (99) COMPONENT UNKNOWN (2) P, BETWEEN COWL & (21) FUEL FEED LINE (MAIN TANK REAR BULKHEAD TO FUEL PUMP) (3) B, BEHIND REAR BULKHEAD (22) FUEL FEED LINE (AUXILIARY (4) Y, F, & P II COMPONENT SOURCE TANK TO FUEL PUMP) (5) Z, P, & B (23) FUEL RETURN LINE (FUEL (6) D, DISTRIBUTED PUMP TO TANK) (1) OEM (F, P & B) (24) INLINE FUEL FILTER (2) AFTER MARKET (9) UNKNOWN (25) FUEL LINE (PUMP TO (9) UNKNOWN CARBURETOR OR INJECTOR PUMP) (26) CARBURETOR TO INJECTOR PUMP SECOND DIGIT (27) FUEL PUMP (LATERAL LOCATION) III TYPE OF DAMAGE (29) DELIVERY SYSTEM, DETAILS UNKNOWN (1) L, LEFT (1) DENTED/CRUSHED (2) C, CENTER (2) PUNCTURED (3) R. RIGHT **EVAPORATIVE EMISSION CONTROL SYSTEM** (3) RUPTURED (4) Y, LEFT CENTER (L & C) (4) SEVERED/GROSS TEARS (5) Z, RIGHT CENTER (R & C) (31) ATMOSPHERIC VENT PIPE (5) DISCONNECTED/DEFEATED (6) D, DISTRIBUTED (NON-EEC EQUIPPED) (9) UNKNOWN (F, P & B) (32) EEC PIPE (VAPOR CANISTER (9) UNKNOWN

TO CARBURETOR)

Duplicate columns 1-8 Module F R Format C from the previous card. 9 10 1		Fire	FR-1
WAS THERE FIRE IN  (0) NO <u>SKIP PAC</u> (1) YES <u>COMPLE</u>	3E.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE  (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE  (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	17

PROVIDE NOTES IF FIRE OCCURRED.

	Duplicate columns 1-8 from the previous card.		E <u>D</u> Format	0 1	EXTERIOR DAMAGE	ED-1
	HOOD PERFORM		DES:		STEERING COL FLEXIBLE COUPLING FLEXIBLE COUPLING TYPE	G
	(0) NO (1) YES (8) NOT APPLIC (9) UNKNOWN				(0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE (CIRCLE EACH)	9 26
	HOOD LATCH(ES)-		-RELEASED	<u>0</u>	(7) OTHER:	
			-DAMAGED	14	COUPLINGDAMAGE	D <u>9</u>
			-JAMMED	15	(USE CODES FROM <u>HOOD</u> PERFORMANCE) -SEPARA' (COMPLE	27 TED <u>9</u>
	HOOD HINGES-	-LEFT,	DAMAGED	16	(3.3	
		-LEFT,	SEPARATED (COMPLETE)			
		-RIGHT,	DAMAGED	18	ENG COMPART TELESCOPING UNIT	
		-RIGHT,	SEPARATED (COMPLETE)	<u>O</u>	TYPE OF UNIT  (00) NONE INSTALLED  (01) - (07) SEE UNITS ON PAGE ED-2  (88) NOT COLLECTED	8 8 30
	HOOD REMAINED OF	N VEHICLE		20	(97) OTHER:	
	REAR EDGE OF HOC	DD-	-ELEVATED	$\frac{1}{21}$	ORIGINAL LENGTH (mm)	
	-o	ONTACTED	WINDSHIELD	27 8 23	F (OR H):	
	-PI	ENETRATED	WINDSHIELD	8/23	TELESCOPED LENGTH (mm)	
	HOOD LATCH LOCAT	ΓΙΟΝ			G:	
	(1) FRONT OF VE (2) COWL AREA (3) SIDE (8) NOT APPLICA (9) UNKNOWN			24	DIFFERENCE (mm)  F (OR H) - G  (IF LESS THAN 15mm, ENTER *000*.)  (888) NOT COLLECTED	
1	ENGINE OR TRANS  SEPARATION (COMP  (0) NO (1) YES (9) UNKNOWN		Mount	<u>)</u>	(991) NOT MEASURED/NO COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN	8 8 8 33

		EXTERIOR DAMAGE	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE?  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>₿</u>	LEFT DOORS HOW DID DOORS OPEN DURING COLLISION?	
LEFT PILLARS  PILLARS SEPARATED COMPLETELY -  USE CODES:  (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	0	USE CODES:  (0) DOOR DID NOT OPEN  OPENED BECAUSE OF  (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN (8) NOT APPLICABLE (NO DOOR)	
-A-PILLAR, UPPER	35 <u>D</u> 36	(9) UNKNOWN -FRONT	0 43 Q 44
-B-PILLAR, UPPER LOWER	<u>O</u> 37	DOORS JAMMED CLOSED-  USE CODES:  (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	
-C-PILLAR, UPPER LOWER -D-PILLAR, UPPER	0 39 40	(9) UNKNOWN -FRONT -REAR	<b>⊘</b> 45 <b>1</b> 46
-D-PILLAR, UPPER	<u>O</u> 41 <u>Y</u> 42	-	
<b>2</b> 2		· ·	

BEST AVAILABL					
		EXTERIOR DAMAGE	ED-3		
		OTHER REAR DAMAGE			
REAR DOOR REAR DOOR TYPE		WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION?	2		
<ul> <li>(0) NO DOOR (INCLUDES PICKUPS)</li> <li>(1) HATCHBACK</li> <li>(2) ONE-WAY TAILGATE</li> <li>(3) TWO-WAY TAILGATE</li> <li>(4) CLAMSHELL/DISAPPEARING</li> </ul>	2/47	(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	50		
TAILGATE (5) SINGLE DOOR (6) DOUBLE DOOR (9) UNKNOWN		SPARE TIRE  (0) NO SPARE TIRE  (1) NOT ATTACHED BEFORE COLLISION	8		
Hatchback		(2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (8) NOT COLLECTED	31		
One-way		(9) UNKNOWN			
Two-way or or		TRAILER HITCH TYPE  (0) NO HITCH	2		
Clamshell		BALL-AND-SOCKET TYPES  (1) TEMPORARY FRAMEWORK (E.G.	52		
Single door		RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON-			
Double door		EQUALIZING) (4) LOAD EQUALIZING OTHER TYPES			
HOW DID DOOR OPEN DURING COLLISION?		<ul><li>(5) RING-AND-PINTLE</li><li>(6) FIFTH-WHEEL (INCL. P/U)</li><li>(7) OTHER (E.G. CLEVIS-AND-PIN)</li></ul>			
(0) DOOR DID NOT OPEN OPENED BECAUSE OF	<u>Ø</u>	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED			
(1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION		TRAILER TYPE (AT TIME OF COLLISION)	•		
(5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN		(0) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER	<u>&amp;</u> 53		
(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN		(4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN			
DOOR JAMMED CLOSED	0	(9) UNKNOWN			
(0) NO - (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	49	-			

		EXTERIOR DAMAGE	ED-4
RIGHT-SIDE BODY MOUNT  DID BODY MOUNT SEPARATE?  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<b>9</b> 54	RIGHT DOORS  HOW DID DOORS OPEN DURING COLLISION?  USE CODES:	
RIGHT PILLARS  PILLARS SEPARATED COMPLETELY -  USE CODES:  (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(00) DOOR DID NOT OPEN  OPENED BECAUSE OF  (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER	<u>O</u> 55	(98) NOT APPLICABLE (NO DOOR) (99) UNKNOWN	00
LOWER	<u>O</u> 56	-FRONT -REAR	63 64
-B-PILLAR, UPPER	<u>0</u>	DOORS JAMMED CLOSED-	65 66
_ LOWER	<u><b>O</b></u> 58	USE CODES:  (0) NO (1) YES	
-C-PILLAR, UPPER	<b>O</b> 59	(8) NOT APPLICABLE <i>(NO DOOR)</i> (9) UNKNOWN	0
LOWER	<u>Q</u>	-FRONT -REAR	<u>5</u> 7
-D-PILLAR, UPPER	<b>⊘</b> 61	•	68
LOWER	<u>Ø</u>	VAN REAR DOOR TYPE  (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) -(9) UNKNOWN	<b>8</b>

EXTERIOR DAMAGE ED-5 WINDSHIELD DAMAGE WINDSHIELD MARK ON CASE VEHICLE: WINDSHIELD CRACKED (0) NO **SOLAR TINT** (1) YES (8) NOT APPLICABLE (9) UNKNOWN **Carlite** WINDSHIELD BROKEN D (PLASTIC INTERLAYER TORN) **LAMINATED** (0) NO SUN VISOR AS-1 (1) YES (8) NOT APPLICABLE DOT-FF FM-M (9) UNKNOWN 8 CRACKED OR BROKEN BY OCCUPANT CONTACT (0) NO (1) YES (8) NOT APPLICABLE WINDSHIELD CODE (9) UNKNOWN (97) DESCRIBED BUT NOT CODED (98) NOT APPLICABLE (NO WINDSHIELD) **EXTENT OF BOND SEPARATION** (99) UNKNOWN (0) NONE (1) 1 - 20% Roof (2) 21 - 40 (3) 41 - 60 DID T-ROOF/SUN ROOF OPEN DURING COLLISION? (4) 61 - 80 (5) 81 - 99 (6) TOTAL (0) NO (7) SEPARATED, AMOUNT (1) YES UNKNOWN (8) NOT APPLICABLE (8) NOT APPLICABLE (NOT A T-ROOF OR SUN ROOF) (9) UNKNOWN (9) UNKNOWN LOCATE AREA OF WINDSHIELD INTEREST OR DAMAGE WITH DIMENSIONS (VERTICAL & HORIZONTAL) ON THIS DIAGRAM OF THE WINDSHIELD AS VIEWED FROM <u>INSIDE</u>. Cracked due to driver hand conact 14 21 -R

Duplicate columns 1-8 Module S C Format from the previous card. 9 10	0 1	STEERING WHEEL AND COLUMN	SC-1
- STEERING WHEEL		STEERING WHEEL POSITION AT TIME OF COLLISION	
STEERING WHEEL RIM DAMAGE  (0) NONE (1) DEFORMED SLIGHTLY	13	IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED?  EXAMPLES	
(2) SEVERELY BENT (3) BROKEN (9) UNKNOWN		O'CLOCK = 1 2 O'CLOCK = 0 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	4	(NORMAL STRAIGHT AHEAD)  O'CLOCK = 12	
STEERING WHL SPOKE DAMAGE		STEERING WHEEL	
(0) NONE -(1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	ENERGY ABSORBING DEVICE  (1) EXAMPLES:  BARRACUDA, 70-74  CHALLENGER, 70-74  CAPRI, 71-77	
		4	:
STEERING COLUMN OPTIONS		(2) EXAMPLES:  OMNI, 78 -  HORIZON, 78 -	
TILT FEATURE		TYPE OF DEVICE	
<ul> <li>(0) NOT EQUIPPED</li> <li>(1) YES, EQUIPPED, UNK POSITION</li> <li>(2) UP</li> <li>(3) MIDDLE</li> <li>(4) LOWER</li> <li>(9) UNKNOWN IF EQUIPPED</li> </ul>	16	(0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED	8 19
SWING-AWAY FEATURE		ORIGINAL DIMENSION (mm) A:	
(0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	0	DAMAGE DIMENSION (mm) B:	
TELESCOPING FEATURE		DIFFERENCE (mm) A - B	
(0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>C</u> 18	(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 22

		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN		STEERING WHEEL (CONTINUED)	
ENERGY ABSORBING DEVICE		,	
TYPE OF DEVICE * (IF 27 OR 28)		STEERING WHEEL HUB DAMAGE	
(00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN	8 8	(0) NONE (1) OCCUPANT CONTACT (2) AIRBAG	<u>Ø</u>
ORIGINAL LENGTH (mm)		(3) OTHER	
C:			
COMPRESSED LENGTH (mm)			
D:			
BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE)			
COMPRESSION (OR EXTRUSION) (mm)			
C - D (OR E) (TOLERANCE: ±10)			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 27		
* (ADD A & B FOR TOTAL COMPRESSION)			
SHEAR CAPSULE SEPARATION (mm)			
S (USE AVG. OF LEFT & RIGHT CAPSULES.)			
RT:			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT			
SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8		
COLUMN VERTICAL ROTATION	`	-	
(0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	<b>₽</b> 31		
COLUMN LATERAL ROTATION		_=	
(0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	<u>0</u>		

- - - ·

	17 4	<b>~</b> • •	101	1 6 1 7
INTRUSION IT-1	11-1	ואו		 11/1


	T						
		(All Mea	ters)	Dominant			
Location of Intrusion	Intruded Component	Comparison Value	_	truded Value	=	Intrusion	Crush Direction
			_		=	·	
		-	_		=		
		-	_		=		
		-			=		
		-	_		=		
		-	_		=		
		-			=		
		-	_		=		

# OCCUPANT CONTACT WORKSHEET

	Interior	Occupant	Body		Confidence Level of
	Component	No. if	Region		Contact
Contact	Contacted	Known	if Known	Supporting Physical Evidence	Point
Α	Lt sunvisor	Driver	Face	Skin	1
В	Upper A- pillar	Driver	Lt f arm or face	Short hairs	2
С	Rear-view mirror	Driver	Rt Hand	Short hairs and oil	2
D	Lt front door	Driver	Lt side	Cracked and scuffed	2
E	Lt front door armrest	Driver	Lt side	Scuffed	2
F	Knee bolster	Driver	Lt knee	Scuffed	1
G	Knee bolster	Driver	Lt knee	Scuffed	1
Н	Knee bolster	Driver	Rt knee	Scuffed	1
<u> </u>	Knee bolster	Driver	Rt knee	Scuffed	1
J	Windshield	Driver	Lt hand	Cracked	1
K					·
L					
M					

### VEHICLE OCCUPANT CONTACT DIAGRAM

### J - windshield - cracked



### Intrusion IT-3

### CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

#### FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

#### SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.

(1)	LEFT	(3)	RIGHT	•••••			INDIVIDUAL SEAT
(1)	LEFT	(2)	CENTER	(3)	RIGHT		BENCH: FULL WIDTH 3 PASSENGER
(1)	LEFT		LEFT CENTER		RIGHT (3) RIGHTCENTER		BENCH: FULL WIDTH 4 PASSENGER
(1)	LEFT	(2)	CENTER		RIGHT & AISLE SPACE		BENCH: PARTIAL WIDTH, LEFT
	LEFT & SPACE	(2)	CENTER		RIGHT &SPACE	••••••	BENCH: PARTIAL WIDTH, CENTERED
(4)	ENTIRE \	/EH	ICLE WIDTH				CARGO AREA

#### **EXAMPLES**

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

#### PASSENGER CAR 5 PASSENGERS

#### VAN 12 PASSENGER CAPACITY

X			X	11			13	
x	X	X				21	22	25
x	<b>X</b> :	X				31	<i>32</i>	35
x	X	x	X	41	42	46	43	

### CODES FOR COLUMN F, MEASUREMENT AXIS

- (X) X-AXIS (FORE & AFT)
- (Y) Y-AXIS (LATERAL)
- (Z) Z-AXIS (VERTICAL)

### CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT NUMBER	INJURY NUMBER	CONTACT
(00)	(00)	- NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97)	(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
(99)	(00) OR (99)	UNKNOWN IF CONTACT

#### INTRUSION IT-4

### CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

#### INDIVIDUAL COMPONENT

#### INTERNAL

(01) INSTRUMENT PANEL

(02) FIRE WALL (03) TOE PAN

(04) FLOOR PAN

(05) STEERING COLUMN

(06) WINDSHIELD

(07) WINDSHIELD HEADER

(08) A-PILLAR

(09) DOOR PANEL OR SIDE PANEL

(10) WINDOW FRAME

(11) B-PILLAR

(12) C-PILLAR

(13) D-PILLAR

(14) ROOF SIDE RAILS

(15) ROOF OR CONVERTIBLE TOP

(16) BACKLIGHT HEADER

(17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE

(18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(21) FIFTH SEAT-BACK SURFACE **SEAT-BACK BACK SURFACE** 

(22) BACK PANEL/BACK DOOR SURFACE

(23) SEAT CUSHION SURFACE/EDGE

(24) CONSOLE

(25) OTHER (DESCRIBE)

(26) UNKNOWN INTERNAL SURFACES

(28) TRANSMISSION TUNNEL (HUMP)

(29) SIDE FOOTWELL PANEL (KICKPANEL)

(30) SILL

### **EXTERNAL**

(43) HOOD

(44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE

(45) OUTSIDE SURFACE OF CASE VEHICLE

(46) OTHER (E.G. SPARE TIRE, JACK. DESCRIBE.)

(49) UNKNOWN EXTERNAL OBJECT

### GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF ALL THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

(50)WINDSHIELD HEADER

A-PILLAR

ROOF SIDE RAIL

(51)INSTRUMENT PANEL A-PILLAR

DOOR PANEL

(52)INSTRUMENT PANEL A-PILLAR

WINDSHIELD HEADER

(53)DOOR PANEL **B-PILLAR ROOF RAIL** 

(54)DOOR PANEL

A-PILLAR **ROOF RAIL** 

(55)INSTRUMENT PANEL FLOOR PAN

A-PILLAR DOOR FRAME

(56)ROOF RAIL

A-PILLAR **B-PILLAR** 

WINDOW FRAME

(57) ROOF RAIL

A-PILLAR **B-PILLAR** 

C-PILLAR

DOOR PANEL

(58)ROOF **ROOF RAIL** 

WINDOW FRAME

DOOR PANEL

(59)BACKLIGHT HEADER

**ROOF** C-PILLAR

THIRD SEAT-BACK

(60)ROOF **ROOF RAIL** A-PILLAR

**B-PILLAR** C-PILLAR

WINDOW FRAME DOOR PANEL FLOOR PAN

(61)INSTRUMENT PANEL

**TOE PAN** 

WINDSHIELD HEADER

A-PILLAR **ROOF RAIL** WINDOW FRAME

DOOR PANEL ROOF

(62)ROOF

**ROOF RAIL** C-PILLAR

WINDOW FRAME

FLOOR PAN

SECOND SEAT

DOOR PANEL

(63) ROOF RAIL **ROOF** 

**B-PILLAR** WINDOW FRAME

FLOOR PAN

DOOR PANEL

SECOND SEAT

FRONT SEAT

(64) ROOF RAIL

ROOF OR CONVERTIBLE TOP A-PILLAR

**B-PILLAR** 

WINDOW FRAME

WINDOW HEADER

(65)WINDSHIELD

WINDSHIELD HEADER **ROOF SIDE RAIL** 

(66)WINDSHIELD

WINDSHIELD HEADER

A-PILLAR -

(98)NOT APPLICABLE

(99)UNKNOWN

Duplicate columns 1-8 Module from the previous card.	1 T Format 0 11	12			Inti	RUSION	IT-5
WAS THERE OCCUPANT COM  (0) NO <u>DO NOT</u> ANSWER NEXT  (1) YES <u>ANSWER</u> NEXT QUEST.  (9) UNKNOWN <u>SKIP PAGE</u> .	T QUESTION. <u>SKIP PA</u>		13		ION CATAS' COMPLETE PA SKIP PAGE.		14
from the previous card.  NOTE: Each line in the table below in the tab		12 (card). Dup ORDER: LEF J ON PAGE I	T TO RIGHT			K IN VEHICLE	es.
A B C INTRUDING A INTRUSION OCC. COMPONENT NUMBER SPACE NO. OR OBJECT		F MAXIMUM INTRUSION Y AXIS (cm)		H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14 15-16 17-18	19 20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 1							
0 2							<del></del>
0 3							
0 4							
<u>0 5</u>							
0 6							
0 7	M 7 INTRUSIONS.						
Duplicate columns 1-8 Module 1 from the previous card.	T Format 0	<u>3</u> 12	·				
NOTE: IF NO SIDE DOOR INTRUSION, SKIP REMAINDER OF PAGE. SIDE DOOR INTRUSION RESULTED FROM	IF DA DOOF INTRU: NUMBE	R INTRUSI SION (	DOOR CO ION, CODE DAMAGED IMPONENT 1	DMPONENT COMPONE DAMA COMPONE	ENT GED NENT 2	CODES	
INTRUSION NUMBER CAUSE  CODES FOR CAUSE:  13 15 (1) DIRECT IMPACT 16 18 (2) INDUCED DAMAGE 21 (9) UNKNOWN	A	- - -	_ _ _ _	25	- (	O) NONE 1) A-PILLAR 2) B-PILLAR 3) C-PILLAR 4) LATCH/STRI 5) HINGES 7) OTHER: 8) NOT APPLIC 9) UNKNOWN	KER -

Duplicate columns 1-8 from the previous card.

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line.

- ADDITIONAL PAGE --

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES.

CODES FOR B, F, G, H, I, J ON PAGE IT-3

CODES FOR C ON PAGE IT-4

OCCUPANT CONTACT AND INJURY

A INTRUSION NUMBER	B OCC. SPACE NO.	C INTRUDING COMPONENT OR OBJECT		E MAXIMUM INTRUSION X AXIS (cm)	F MAXIMUM INTRUSION Y AXIS (cm)	G MAXIMUM INTRUSION Z AXIS (cm)	H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 8										
0 9										
<u>1</u> <u>0</u>										
11			_							
1 2			_							
1 3										
1 4										
1 5			_							
<u>1</u> 6										
1 7										
1 8				<del></del>	<del></del> .					
<u>1</u> 9										
2 0			_							
2 1			<del></del>					<del></del>		
22								<del></del>		
2 3		<del></del>								
24										
<u>2</u> <u>5</u>								<del></del>		

Duplicate columns 1-8 from the previous card.	Modu		Format 0 1 12	In	ITERIOR DAMAGE	ID-1
CO	(1	) NO ) YES ) NO, an	d OCCUPANT CONTACT	(4) YES, and (8) NOT APPI (9) UNKNOW	DCCUPANT CONTACT ICABLE N	
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS ROOF SIDE RAIL B-PILLAR C-PILLAR D-PILLAR HEADLINING ROOF STRUCTURE T-ROOF/SUN ROOF OTHER: *	LEFT 4 13 Q 15 O 17 O 23 O 25 O 27 O 29 O 31 1 33 P 35 O 37 O 39 8 45 0 43	RIGHT 0 14 0 15 0 20 0 22 0 24 0 25 0 28 0 30 0 34 0 36 0 38 0 48 0 48 44	FRONT FOOT CONTROLS  IGNITION KEYS  REAR VIEW MIRROR  SUNVISOR/FITTINGS (5) LEFT SIDE ONLY (7) BOTH SIDES  WINDSHIELD TOP MOLDINGS  LEFT A-PILLAR (UPPER OR LOWER)  RIGHT A-PILLAR (UPPER OR LOWER)  CENTER CONSOLE  TRANSMISSION SELECTOR LEVER  RIM, HORN, SPOKE	0 45 0 46 3,47 <b>2</b> 48	INSTRUMENT PANEL UPPER PANEL MID PANEL LOWER PANEL ASHTRAY CONTROL KNOBS & LEVERS GLOVE COMPARTMENT AREA INSTRUMENTS PARKING BRAKE RELEASE PARKING BRAKE PEDAL A/C OR UPPER VENT OUTLET: HEATER OR A/C DUCTS RADIO OTHER: *  REAR WINDOW WINDOW HEADER  CONSOLES	64 <b>O</b>   65 <b>O</b>   66 <b>S</b>   67 <b>O</b>   68 <b>O</b>   69
<b>3</b>				4	VERTICAL	70 <b>1</b> 71

MORE THAN ONE ITEM MAY BE NOTED.

Duplicate columns 1-8 from the previous card.  Module S T 9 10			SEATS	Ş	ST-1
FRONT SEAT	DRIVER	PASSENT	FRONT SEAT-BACK	DRIVER	Passen'r
TYPE OF FRONT SEAT  (00) NO SEAT  (01) STANDARD BENCH  (02) SPLIT BACK, 50-50  (03) SPLIT BACK, DRIVER WIDE  (04) SPLIT BACK, PASS. WIDE  (05) BUCKET  (06) CAPTAIN'S CHAIR  (07) INDIV. BENCH, 50-50  (08) INDIV. BENCH, DRIVER WIDE  (09) INDIV. BENCH, PASS. WIDE	0 5	0 5	SEAT-BACK TYPE  (1) FORWARD FOLDING  (2) RIGID  (3) RECLINING  (7) OTHER:  (8) NOT APPLICABLE  (9) UNKNOWN  SEAT-BACK LOCK TYPE	3/30	3
(97) OTHER: (99) UNKNOWN  TYPE OF SEAT MOUNT (1) STANDARD (2) PEDESTAL (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	17	18	(0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	32	33
SWIVEL MECHANISM EQUIPPED(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>O</u> 19	20	LOCKS HELD  (0) NO  (1) YES  (8) NOT APPLICABLE  (9) UNKNOWN	/ 34	35
ORIGINAL EQUIPMENT SEATS . (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	21	1/22	RECLINER MECHANISM HELD (0) NO (1) YES	/ 36	<u></u>
CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	<u>8</u>	(8) NOT APPLICABLE (9) UNKNOWN		
FRONT SEAT DAMAGE  (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	<u>Q</u> 25	26	HEAD RESTRAINT  HEAD RESTRAINT TYPE  (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	38	39
CENTER ARMREST DAMAGED  (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	<u> </u>	7	(9) UNKNOWN  REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>Ø</u>	<u>8</u>
FRONT SEAT ROTATION  (0) NONE APPARENT	0	70	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN	2/42	2 43
(0) NONE PARENT (1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	28	29	HEAD RESTRAINT DAMAGE  (0) NONE  (4) DAMAGED BUT  NOT SEPARATED  (2) SEPARATED  (8) NOT APPLICABLE  (9) UNKNOWN	0 4	<u>ð</u>


-			Se	ATS	ST-2
FRONT SEAT ADJUSTMENT	DRIVER	PASSEN'R	SECOND SEAT (CONT.)		
SEAT ADJUSTMENT TYPE  (0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN  ADJUSTMENT PROVIDED	46	47	(0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	6	<b>§</b>
(1) 2-WAY (2) 4-WAY (3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	48	49	SECOND SEAT-BACK LOCKS	LEFT	Яіднт
SEAT ADJUSTER DAMAGE  (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER:  (8) NOT APPLICABLE (9)-UNKNOWN	<u>O</u> 50	<u>O</u> 51	FOR THE FOLLOWING, USE:  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN		
SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN	<b>8</b> 52	<u>\$</u>	LEFT OR CENTER, EQUIPPED  LEFT OR CENTER, HELD  (3) SEAT FOLDED DOWN  RIGHT, EQUIPPED	0   61 84 8 0	<u>Ø</u> <u>8</u> 64 ∠ 66
PRE-CRASH POSITION  (1) FORWARD  (2) MIDDLE  (3) REARWARD  (8) ÑOT APPLICABLE  (9) UNKNOWN	3	<u>3</u>	RIGHT, HELD  (3) SEAT FOLDED DOWN  THIRD SEAT	65 <b>&amp;</b> 67	
SECOND SEAT  TYPE OF SECOND SEAT  (0) NONE (1) NON-FOLDING (2) FOLDING (3) CAPTAIN'S CHAIR	<b>L</b> EFT <b>Z</b> 56	RIGHT 2	EQUIPPED  BACKREST DAMAGED  CUSHION DAMAGED	71 <u>Ø</u>	70 0 72 0 74
(4) JUMP SEAT (5) INTEGRAL CHILD SEAT (6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN  SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE)  (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	<u>Ø</u> 58	O 59	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS  (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN  Applies to any rear-seat position	75	<u>!</u>

Duplicate columns 1-8 from the previous card.  Module A B Format 0 11		AIRBAG A	4B-1
DRIVER SIDE  LOCATION OF AIRBAG  STEERING WHEEL  EQUIPPED  (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	13	PASSENGER SIDE  LOCATION OF AIRBAG  INSTRUMENT PANEL (GLOVE BOX)  EQUIPPED  (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	1 16
DEPLOYED  (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	14	DEPLOYED  (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	17
CONDITION OF AIRBAG STEERING WHEEL  (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN - (8) NOT APPLICABLE (NOT EQUIPPEDNOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	<b>6</b>	CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX)  (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPEDINGT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	O 18
DRIVER SIDE  AIRBAG  STEERING WHEEL  TETHER  (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	PASSENGER SIDE  AIRBAG INSTRUMENT PANEL (GLOVE BOX)  TETHER  (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	
MARKED BY CONTACT  (0) NO (7) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u>)</u>	MARKED BY CONTACT  = (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u></u> \[ \frac{\omega}{22} \]


### AIRBAG AB-2

### AIRBAG NUMBER ON DRIVER SIDE:





**Driver Airbag Door** 




Vents: Y N
if yes, how many: \_\_\_\_2

at 11 and 1 oclock

Tethers: Y N
if yes, how many: \_\_\_


### AIRBAG NUMBER ON PASSENGER SIDE:

### Passenger Airbag



Passenger Airbag Door

Single Door



Vents: Y N
if yes, how many: 1
at 3 oclock

Tethers: Y N
if yes, how many: 2

#### NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,
OCCUPANT INFORMATION AND INJURY CLASSIFICATION,
ARE TO BE FILLED IN
FOR EACH CASE VEHICLE OCCUPANT,
WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.


Duplicate columns 1-8 Module O C Format 0 from the previous card.	2 12	Occupant Information	OC-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER  ROLE OF OCCUPANT AT 1ST IMPACT  (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	<u>Q</u> <u>1</u> 13 14 <u>1</u> 15	PHYSICAL DESCRIPTION  AGE IN YEARS  (00) LESS THAN 1 YEAR  (98) 98 YEARS OR OLDER  (99) UNKNOWN  AGE IN MONTHS  (00) LESS THAN 1 MONTH  (25) 25 MONTHS OR OLDER  (99) UNKNOWN	4 1 20 21 2 5 22 23
OCCUPANT POSITION  ROW LOCATION  (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	MASS (kg) (999) UNKNOWN (190 lb)  HEIGHT (cm) (999) UNKNOWN (5 ft, 8 in)  SEX (1) MALE (2) FEMALE (9) UNKNOWN	0 8 6 24 25 26 1 7 3 27 28 29
(9) UNKNOWN  LATERAL LOCATION  (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN  POSTURE  (10) SITTING ON SEAT (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS)  (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON SEAT (40) STANDING, EXTERNAL TO PASSENGER COMPARTMENT (50) IN BASSINET (60) IN CHILD HARNESS (70) LYING ON SEAT (85) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK (87) LYING/SITTING, EXTERNAL TO		MEDICAL CONDITIONS  TREATMENT/MORTALITY  (00) NONE  (01) FIRST AID AT SCENE  (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED  (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS  (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT  (05) FATAL, DEAD AT SCENE  (06) FATAL, DEAD WITHIN 24 HOURS  (08) FATAL, DEAD WITHIN 24 HOURS  (08) FATAL, DEAD WITHIN 24 HOURS  (09) FATAL, DEAD WITHIN 10 HOURS  (10) FATAL DEAD WITHIN 10 HOURS  (11) FATAL DEAD WITHIN UNKNOWN PERIOD  (12) UNKNOWN  INJURY SEVERITY SCORE (ISS)  (13) UNKNOWN  NON-IMPACT MED. CONDITIONS  (14) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL)  (15) PRE-CRASH FATAL (DROWNING)  (16) POST-CRASH FATAL (DROWNING)  (17) OTHER:	O 1 31 32 34 D 35

-		OCCUPANT INFORMATION	OC-2
MEDICAL CONDITIONS (CONT.)  POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	<u>Z</u>	CHILD SEAT TYPE  (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN  CHILD SEAT MAKE/MODEL	8 41
ACTIVE RESTRAINT SYSTEM  (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN  ACTIVE RESTRAINT SYSTEM USAGE  (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN  PASSIVE RESTRAINT SYSTEM  (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN	3 37 0 38	EJECTION  (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED  AREA OF EJECTION  (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, RIGHT SIDE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	9844
(0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	2 40	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION  (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	1

-		OCCUPANT INFORMATION (	OC-3
OCCUPANT EYEWEAR  (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN	47	SOURCE OF INFORMATION  (0) INTERVIEW (1) HOSPITAL (2) AUTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN	<u>O</u> 48

### OCCUPANT INFORMATION OC-4

#### INDICATE LOCATION OF INJURIES.





Duplicate columns 1-8 from the previous card.

INJURY CLASSIFICATION IC-1

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.


		la unovi	$\frown$	ASSIFICATION
( )	CCHPANT	INJURY		ASSIFICATION

						PRIM	IARY (	OIC		A	SSOC	IATE	OIC		COMMEN
OCCUPANT NUMBER	INJURY NUMBER	PROBAL START I IN 1ST C	BILITY (HOR WITH MOST CONTACT AF	N ORDER OF IZONTALLY). PROBABLE REA COLUMN. LE CONTACT	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY 15	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY 10	
3-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30	
21	01	10	14		F	<u>5</u>	A	Į	1	_		_			
<b>†</b>	02	10	14		E	۷	A	I	1	_		_		_	
	03	56			K	4	A	Į	1	_				_	
	<u>o 4</u>	<u>56</u>					A				_		_		
					-	_	_		_	_	_	_			
					-				_	_	_		_		
					_				_		_				
<u>v</u> i					_	_				_				-	•
					_			_	_		_	_			
					_			_		_				-	
Occupant Number 10f each line					_	_		_	·					_	
					_	_	_			_	_	_		-	
					_	_	_	_	-	_		_	_	-	
					_		_	_	-	_			<u> </u>	-	
					_				-	_	_		_	_	
					_	_		_	-	_	_	_	_	-	
					_				-	_		_	_		•
=	_==						_		_	-	_				

## INJURY CLASSIFICATION IC-2

### CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

FRONT	OF PASSENGER COMPARTMENT	SIDES	
(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING	(20)	SURFACE OF SIDE INTERIOR
(12)		(19)	
( /		(13)	
(05)	INSTRUMENT PANEL (SPECIFIC AREA UNKNOWN)	(24)	
(54)		(24)	COATHOOK
		(00)	MINIDOM OLAGO (OIDE)
(55)		(22)	
(56)		<b>(2</b> 1)	WINDOW FRAMES (SIDE)
(81)			
(02)	GLOVE COMPARTMENT AREA	(26)	ROOF SIDE RAIL
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(14)	A-PILLAR
	-	(15)	B-PILLAR
(57)	BENEATH INSTRUMENT PANEL	(16)	C-PILLAR
(53)		(17)	
(48)		(,	5 · 122 · 11
(86)		FLOOR	
(00)	VEITHORE CONCOLE		EL COR
(00)	FOOT CONTROLS /INICL BARRING BRAKE BEDALL	(40)	
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(27)	
		(44)	
(09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)	(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE
(65)	STEERING WHEEL	(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)
(66)	STEERING WHEEL COLUMN	(91)	KICKPANEL
<sup>-</sup> (59)	TRANSMISSION LEVER ON COLUMN	` '	
٧٠,		Roof	
(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)	(25)	ROOF OR CONVERTIBLE TOP
(82)	INSTRUMENT(S)		
	· ·	(10)	• • • • • • • • • • • • • • • • • • • •
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	(26)	
(84)	PARKING BRAKE HANDLE IN FRONT	(24)	
(67)	IGNITION KEY	(18)	DOME LIGHT
(06)	MIRROR	(39)	BACKLIGHT HEADER
(04)	HEATER OR AIR CONDITIONING DUCTS	(68)	ROOF MOUNTED CONTROLS/CONSOLE
(01)	AIR CONDITIONING OR VENTILATION OUTLET(S)	(69)	
(08)	RADIO (BUILT IN)	(00)	HOLE BAIT
(58)	ADD-ON TAPE DECK, RADIO, A/C	EVTERIO	OR SURFACE OF CASE VEHICLE
(68)	ROOF MOUNTED CONTROLS/CONSOLES	(37)	OUTSIDE SURFACE OF CASE VEHICLE
_			(SPECIFIC AREA UNKNOWN)
REAR		(35)	HOOD OF CASE VEHICLE
(88)	SURFACE OF REAR INTERIOR	(60)	EXTERIOR OF CASE VEHICLE (E.G.
(23)	REAR WINDOW		OUTSIDE MIRRORS, ANTENNA, TRIM)
	REAR WINDOW HEADER	(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
	REAR SEAT CUSHION & BACK	(63)	TRUNK LID OF CASE VEHICLE
(30)	TIDATIODAT GOGINOIT & DAOR		
INTERIO	R-GENERAL	(64)	TIRES OF CASE VEHICLE
		Provin	Cass Verge & Boundary
	TRANSMISSION SELECTION LEVER (LOCATION UNK.)		CASE VEHICLE BOUNDARY
(59)	TRANSMISSION LEVER ON STEERING COLUMN	(36)	AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE	(70)	HOOD OF OTHER VEHICLE
(07)	PARKING BRAKE HANDLE (LOCATION UNKNOWN)	(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
(84)	PARKING BRAKE HANDLE IN FRONT		OUTSIDE MIRRORS, ANTENNA, TRIM)
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(73)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
(20)	1 00 1 00 11 11 10 ( I 10 10 11 11 11 11 11 11 11 11 11 11 11		
***	EDONIT CEAT DACK/CI	(75)	TRUNK OF OTHER VEHICLE
(29)	FRONT SEAT-BACK(S)	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
(51)		(77)	TIRES OF OTHER VEHICLE
(50)	REAR SEAT CUSHION & BACK	(78)	GROUND
(49)	ARMREST ON SEAT	(79)	WATER
(89)	UNDER SEAT BOTTOM	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND.
` '		()	OR WATER. PLEASE DESCRIBE.)
(33)	RESTRAINT SYSTEM HARDWARE		THE TENDE DESCRIBE,
		DENETO	ATING OBJECTS
(34)			
(87)	· ·	` '	OTHER VEHICLE
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(72)	OBJECTS (DESCRIBE)
(46)	AIRBAG GAS		
(48)	KNEE RESTRAINT	MISCELL	ANEOUS
(30)	HEAD RESTRAINT	(00)	NO CONTACT (INVALID FIELD FÖRM CODE)
(42)	CHILD SEAT RESTRAINTS	(38)	OTHER (E.G. FIRE. DESCRIBE)
	CHILD SEAT	_ ' '	_SPARE TIRE
	INTERIOR LOOSE OBJECT	(,	INDUCED
	OTHER OCCUPANT(S)	i	
(32)		(97)	
	INTERNAL FLYING GLASS (FROM ANY SOURCE)	(98)	
(41)	UNKNOWN INTERIOR SURFACE		HYPEREXTENSION/COMPRESSION
		(99)	UNKNOWN AREA OF CONTACT



### INJURY CLASSIFICATION IC-4

### CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

### 1 BODY REGION

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

### 3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

### 4 SYSTEM/ORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (I) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

### 2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

SEVERITY 5
SYSTEM/ORGAN 4
LESION 9
ASPECT 0
BODY REGION 1

5 SEVERITY (OR "AIS", ABBREVIATED INJURY SCALE)

- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN

**.** ,

FO

Control (Steller Land)

Contro







st Avail





Best Available











Best Available











st Availat





et Availat











20100#22





































































